

Information Bulletin

Product Group:	Actuators	Valves	Air Treatment	Factory Automation	Other Products	
Title:	PC/RC5,13 Latch type obsolete					
Catalogue:						
Date of Issue:	May 6, 2010					
Bulletin No:	IBL-KPL-276/10					

PC/RC5, 13 Latch type solenoid valve Obsolete

The solenoid supplier will stop to supply the following item and we can not continue to supply them. Please refer to the contents and consider to change.

1) Object: Pilot operated solenoid valve, PCL(RCL)245 and PCL(RCL)2413 include customized item related to those valves.

2) Replacement

Current item		Replacement	
PCL245	Latch type solenoid (One side solenoid)	PCD245	Double solenoid (Both side solenoid)
RCL245		RCD245	
PCL2413		PCD2413	
RCL2413		RCD2413	

***Interface of manifold of obsolete item is same as those of replacement.

3) Changed point

Current item		Replacement	
PCL5-D24-CL5	Lead wire with connector for latch type solenoid (3 pins)	PC5-D24-CL5*	Lead wire with connector for standard solenoid (2 pins)

*** Replacement (PCD245 and etc) is double solenoid and need two PC5-D24-CL5.

3) Time to stop supplying: October 30, 2010 or as soon as we consume our stock.

Reference Drawing.


Current model : PCL245/RCL245	Replacement : PCD245/RCD245
-------------------------------	-----------------------------

Action Required					Distribution		
Discard old Bulletin	Request new Catalogue	Add bulletin to Catalogue	Contact Factory	Check Stocks	1	2	3

Issued from the DSO Department, Parker Pneumatic, Lichfield – UK
Any amendments or additions to be forwarded to the DSO Department,
Tel No 00 44 (0)1543 483834

Information Bulletin

Product Group:	Actuators	Valves	Air Treatment	Factory Automation	Other Products	
Title:	PC/RC5,13 Latch type obsolete					
Catalogue:						
Date of Issue:	May 6, 2010					
Bulletin No:	IBL-KPL-276/10					




Current : PCL2413/RCL2413	Replacement : PCD2413/RCD2413
---------------------------	-------------------------------

Action Required					Distribution			2
Discard old Bulletin	Request new Catalogue	Add bulletin to Catalogue	Contact Factory	Check Stocks	1	2	3	
Issued from the DSO Department, Parker Pneumatic, Lichfield – UK Any amendments or additions to be forwarded to the DSO Department, Tel No 00 44 (0)1543 483834								

Information Bulletin

Product Group:	Actuators	Valves	Air Treatment	Factory Automation	Other Products	
Title:	PC/RC5,13 Latch type obsolete					
Catalogue:						
Date of Issue:	May 6, 2010					
Bulletin No:	IBL-KPL-276/10					



Please refer to our catalogue in the detail. www.parkerkuroda.com

With best regards,

XXXX XXXXX
 Sales Dept.
 Kuroda Pneumatics LTD.
 Tel: +81-45-870-1510
 Mob:+81-90-6111-3403
 E-mail: XXXXXX@kpl.parker.com

Action Required					Distribution			3
Discard old Bulletin	Request new Catalogue	Add bulletin to Catalogue	Contact Factory	Check Stocks	1	2	3	
Issued from the DSO Department, Parker Pneumatic, Lichfield – UK Any amendments or additions to be forwarded to the DSO Department, Tel No 00 44 (0)1543 483834								

Information Bulletin

Product Group:	Actuators	Valves	Air Treatment	Factory Automation	Other Products	
Title:	PC/RC5,13 Latch type obsolete					
Catalogue:						
Date of Issue:	May 6, 2010					
Bulletin No:	IBL-KPL-276/10					

Action Required	Distribution	4
------------------------	---------------------	---

Discard old Bulletin	Request new Catalogue	Add bulletin to Catalogue	Contact Factory	Check Stocks	1	2	3
----------------------	-----------------------	---------------------------	-----------------	--------------	---	---	---

<p>Issued from the DSO Department, Parker Pneumatic, Lichfield – UK Any amendments or additions to be forwarded to the DSO Department, Tel No 00 44 (0)1543 483834</p>
